

**FORM 12**  
**BUILDING WARRANT OF FITNESS**  
Section 108, Building Act 2004



Compliance schedule number: HCS/99/00256  
Compliance schedule anniversary date: 16th December

WOF expiry: 16th December 2019

**BUILDING DETAILS**

**Building name:** Vector House  
**Street address of building:** 101 Carlton Gore Road, Newmarket, Auckland  
**Legal description of land where building is located:** Lot 1 DP 191560  
**Location of building within site:**  
**Current, lawfully established use:** Offices/Carpark  
**Year first constructed:** Not known  
**Highest fire hazard category for building use:** Not known

**OWNER DETAILS**

**Name:** Argosy Property Number 1 Limited  
**Mailing address:** PO Box 90214, Victoria Street West, Auckland 1142  
**Contact name:** Craig Dodds | Compliance Manager  
**Contact phone:** 09 304 3431  
**Contact email:** cdodds@argosy.co.nz  
**Contact fax:** 09 302 0996

**AGENT DETAILS**

**Name of agent:** Building Compliance Group Ltd (BC Group)  
**Contact person:** Carolyn Davies  
**Phone:** (09) 577 1061  
**Relationship to owner:** Owner authorised agent  
**Mailing address:** PO Box 14 675, Panmure, Auckland  
**Email:** enquiries@bcgroup.co.nz  
**Fax:** (09) 577 1063

**SPECIFIED SYSTEMS**

Automatic Sprinkler System or Systems of Automatic Protectio...	Passenger Carrying Lifts
Automatic Gas Flood System	Mechanical Ventilation & Air Conditioning Systems
Emergency Warning systems for fire or other dangers	Signs for Systems 1-13
Automatic Doors	Final Exit (means of escape to final exit)
Egress Controlled Doors	Fire Separations (means of escape to final exits)
Emergency Lighting Systems	Signs for Communicating Information for Evacuation (means of...
Any Automatic Back-flow Prevention connected to a potable wa...	Smoke Separation ( means of escape to final exit)

**WARRANT**

The inspection, maintenance, and reporting procedures of the compliance schedule for the above building have been fully complied with during the 12 months prior to the date stated below.

The Compliance Schedule and records are kept at the building address stated above. A copy is also kept at BC Group, 21 Ti Rakau Drive, Pakuranga, Auckland.

Signature of agent on behalf of and with the authority of the owner:

Carolyn Davies (Owner's Agent)

16/12/2018

Name & Position

Signature

Date