



Form 12a Certificate of Compliance



Inspection, Maintenance and Reporting Procedures

Form 12a Section 108 (3) (c), Building Act 2004
Compliance Schedule Anniversary Date : 22nd November

Building

Street Address **107 Carlton Gore Road, Newmarket, Auckland**
Known As **ANZ / National Bank Ltd Head Office**
Legal Description **LOT 4 DP 209572**
Building Name **ANZ / National Bank Ltd Head Office**
Location Within Site
Level/Unit Number

Owner

Name **Argosy Property Number 1 Limited**
Mailing Address **PO Box 90214
Victoria Street West
Auckland 1142**

Specified Systems

The inspection, maintenance and reporting procedures of Compliance Schedule 200400235, reissued 27/11/2012, have been fully complied with during the 12 months prior to the date stated below in relation to the following specified systems:

Description of Specified System	Compliance Schedule Number 200400235
Signs for Systems 1-13	
Final Exit (means of escape to final exit)	
Fire Separations (means of escape to final exits)	
Signs for Communicating Information for Evacuation (means of escape to final exit)	
Smoke Separation (means of escape to final exit)	

Reports

The records of inspections and annual reports supporting these certificates are available from building owners IQP warrant of fitness agent BC Group, 21 Ti Rakau Drive, Pakuranga, Auckland, PO Box 14 675, Panmure, Auckland, Phone (09) 577 1061, Fax (09) 577 1063, Email enquiries@bcgroup.co.nz

The signature below indicates certification and annual reports for all above systems supplied by IQP contractors have been sighted and are available at the location of the owners IQP agent.

Name Ian Petrie Signed _____

Position BC Group. Approved IQP. IQP Reg. No. 110185

Date 22/11/2018 Council Auckland Council (Central)